

10/10/2007

UNION County
Groundwater Contamination Inventory
South Carolina - 2007

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
UNION County					
AMOCO STATION UNION	PETRO	UST	BLWM		Site ID #14944. RBCA Classification 1D4. Active Corrective Action.
BOBS GULF	PETRO	UST	BLWM		Site ID #12889. RBCA Classification 2BB8. Awaiting Funding.
CABANISS SERVICE STATION	PETRO	UST	BLWM		Site ID #08985. RBCA Classification 2AA4. Active Corrective Action.
CONSO PRODUCTS	VOC	PPL	BOW		Site is in monitoring phase. Waste water line and basin.
ENMARK 560	PETRO	UST	BLWM		Site ID #08995. RBCA Classification 3AA5. Inactive.
EUBANKS GROCERY	PETRO	UST	BLWM		Site ID #08983. RBCA Classification 4AA7. Approved Monitored Natural Attenuation (MNA Awaits)
GREERS SHELL 1	PETRO	UST	BLWM		Site ID #08993. RBCA Classification 4BA8. Awaiting Funding.
GREGORYS STORE	PETRO	UST	BLWM		Site ID #08979. RBCA Classification 2AB4. Active Corrective Action.
HOT SHOTS GULF	PETRO	UST	BLWM		Site ID #12890. RBCA Classification 5A6. Contacted.
J H CROMER SITE	PETRO	UST	BLWM		Site ID #14564. RBCA Classification 2AA4. Active Corrective Action.
JOHNNIES MARKET & MORE	PETRO	UST	BLWM		Site ID #08986. RBCA Classification 3BA1. Conducting Investigation/Risk Assessment.
LIL CRICKET 216	PETRO	UST	BLWM		Site ID #08996. RBCA Classification 3BD5. Inactive.
MCCOY SERVICE CO INC	PETRO	UST	BLWM		Site ID #15360. RBCA Classification 3BA1. Conducting Investigation/Risk Assessment.
SOUTHERN BELL UNION SOC	PETRO	UST	BLWM		Site ID #16443. RBCA Classification 2AA4. Active Corrective Action.
TIMKEN U.S. CORPORATION	VOC, PETRO	PPL	BLWM	SCD041387796	In remediation phase. Formerly Torrington Tyger River Plant.
TORRINGTON COMPANY	PETRO	UST	BLWM		Site ID #08973. RBCA Classification 2BA4. Active Corrective Action.
UNION COUNTY SANITARY LANDFILL	VOC	LF	BLWM		In assessment, monitoring, and remediation phases. Permit # 441001-1101.
UNION INDUSTRIAL SERVICES INC	PETRO	UST	BLWM		Site ID #08952. RBCA Classification 4AA9. Conditional No Further Action (CNFA). Site conditi
UNION MILLS	PETRO, VOC	UST, S/L, AGT	BLWM	SCD047560859	BLWM File # 51382. In assessment and monitoring phases. Plume is discharging to unnamed surface water body.
Total for UNION	19				